



## Room Resistance thermometer

5.1

## Room resistance thermometer

Measuring insert 1 x PT 100 / 2 x PT 100 for dry rooms with

measuring insert open as outdoor thermometer as

well as for wet locations shed measuring insert


For dry rooms

Operating temperature to 70° C

**Enclosure** Plastic housing with galvanized sheet metal base

plate with cable gland

1 x PT100 Order no. 4.20.00.11 2 x PT100 Order no. 4.20.00.12



For dry rooms


Operating temperature to 80° C

**Enclosure** Die-cast aluminum with MS - cable entry M 16 x 1,5

1 x PT100 L.-Nr. 4.20.00.21 2 x PT100 L.-Nr. 4.20.00.22

**Enclosure** Makrolon with plastic cable gland M 16 x 1,5

1 x PT100 L.-Nr. 4.20.00.31 2 x PT100 L.-Nr. 4.20.00.41



## **External resistance thermometer**

With sun protection

Operating temperature to 80° C

**Enclosure** Die-cast aluminum with MS - cable entry M 16 x 1,5

1 x PT100 L.-Nr. 4.20.00.11 2 x PT100 L.-Nr. 4.20.00.12

